



IMPORTADORA
ISIS

Importación, Exportación
y Comercialización de Repuestos
de Vehículos
Ignacio Carrara Pinto #1161, Rancagua.
Fono: 72-2-583570
ventas@importadoraisis.cl



ZEN0737



D:9
L:87
P:29.6
DC:41
C:53.2
CW

HITACHI:CHEVY DIESEL/
COMBO DIESEL/NISSAN
REPARACION ZEN1200

ZEN0790



D:9
L:87
P:36
DC:41
C:53.2
CW

HITACHI:NISSAN

ZEN0791



D:8
L:87
P:28
DC:41
C:53.2
CW

HITACHI:NISSAN PRIMERA
PIÑON ZEN9528

ZEN0792



D:9
L:87
P:33
DC:41
C:53.2
CW

HITACHI:THERMO KING/
ISUZU
REPARACION ZEN1200

ZEN0793



D:8
L:94
P:28
DC:41
C:53.2
CCW

HITACHI:NISSAN SENTRA/
PULSAR 1.6
REPARACION ZEN1207

ZEN0844



D:9
L:87
P:25.9
DC:41
C:53.2
CW

HITACHI:VW LTTD/VOLVO
240D/740D/940 TD
PIÑON ZEN9566

ZEN0892



D:9
L:78.5
P:25.9
DC:44
C:44.9
CCW

SKODA:FELICIA

ZEN1081



D:12
L:92.7
P:37.1
DC:44
C:64.8
CW

FORD:F250-F350

ZEN1608



D:9
L:92
P:35
DC:41
C:64.4
CW

HITACHI:SILVERADO /
KODIAK
PIÑON ZEN13224

ZEN1676



D:12
L:92.7
P:37.2
DC:44
C:64.8
CW

FORD:F SERIES DIESEL
3.6 KW

ZEN1780



D:10
L:95.3
P:39.15
DC:41
C:53.2
CW

HITACHI: NISSAN NAVARA
S14413C

ZEN1858



D:10
L:100
P:36
DC:41
C:64.44
CW

HITACHI:ISUZU NKR. NPR
22402500 (S25120A)

ZEN1860



D:9
L:87
P:29.6
DC:41
C:53.2
CCW

HITACHI:YANMAR

ZEN1861



D:9
L:95.3
P:33
DC:41
C:53.2
CW

HITACHI:ISUZU

ZEN1862



D:9
L:95.3
P:36
DC:41
C:53.2
CW

HITACHI: TERRANO 2.7 Tdi
213095007-213015005

ZEN1865



D:11
L:103.3
P:40.5
DC:41
C:64.44
CCW

HITACHI:ISUZU NKR66
S25168A-S25515A

ZEN1883



D:9
L:100
P:36
DC:41
C:53.2
CW

HITACHI:GRUAS CLARK

ZEN1960



D:9
L:100
P:32.2
DC:41
C:64.44
CW

HITACHI:ISUZU / TCM FD25Z

ZEN2015



D:11
L:100
P:40.5
DC:41
C:64.44
CW

HITACHI:NISSAN
S13118

ZEN2029



D:9
L:96
P:36
DC:41
C:64.44
CW

HITACHI:KOMATSU/ YANMAR
S13160/ S14102



IMPORTADORA
ISIS

Importación, Exportación
y Comercialización de Repuestos
de Vehículos
Ignacio Carrera Pinto #1161, Rancagua.
Fono: 72-2-583570
ventas@importadoraisis.cl



GNP2233



D:11
L:115
P:40

HITACHI:
ISUZU NPR 4BE1/
4BGF1 / 4HF1



BEHI01



D:11
L:104
P:40

HITACHI:
ISUZU 4HF1200/ 4JBD2



BEHI02



D:11
L:132
P:40
DC
IP:
C:

HITACHI:NPR 4.3



ZEN0957



D:20
L:116.8
P:14.7
DC:
C:
CW

mitsubishi:MAZDA/ YALE/
NISSAN / MITSUBISHI
PIÑON ZEN12658/ 12659



ZEN1043



D:18
L:109.8
P:13.32
DC:
C:
CW

MITSUBISHI:FIAT IVECO/

PIÑON ZEN9495



ZEN1046



D:20
L:126
P:14.7
DC:
C:
CW

MITSUBISHI:FUSO CANTER

PIÑON ZEN12812



ZEN1047



D:20
L:119
P:14.7
DC:
C:
CW

MITSUBISHI:L200 1997/
MONTERO 2.3TD/2.5 TD

PIÑON ZEN12812



ZEN1577



D:19
L:116.8
P:14.6
DC:
AE:59.7
CW

MITSUBISHI:HYUNDAI H100
MIGHTY 2.5 TON

PIÑON ZEN12656



ZEN1667



D:19
L:126
P:14.6
DC:
AE:69
CCW

MANDO:KIA BESTA 2.7

PIÑON ZEN13021



ZEN1853



D:20
L:140
P:14.6
DC:
AE:
CW

MITSUBISHI:FUSO



GNP2214



D:19
L:116.8
P:14.6
DC:
AE:59.7
CW

ZEN1577
MITSUBISHI:HYUNDAI H100
MIGHTY 2.5 TON
PIÑON ZEN12656



GNP2218



D:19
L:140
P:14.6
DC:
AE:
CW

MANDO:KIA BESTA 2.5 2.7



GNP2234



D:20
L:119
P:14.7
DC:
C:
CW

MITSUBISHI:L200 1997/
MONTERO 2.3TD/2.5 TD
PIÑON ZEN12812



ZEN0887



D:20
L:110
P:14.7
E:5
C:60
CW

MITSUBISHI:CANTER/
CATERPILLAR 320B



ZEN1563



D:20
L:91
P:14.7
E:5
IP:12
C:54.5
CW

MITSUBISHI
MITSUBISHI L200-MONTERO
MERCEDES



ZEN1661



D:26
L:133.5
P:19.02
E:6
IP:14.0
C:67.9

MITSUBISHI:VOLVO FM/FH
VW 26260
PIÑON ZEN12972



ZEN1808



D:26
L:141
P:19.02
E:6
IP:14.06
CW

MITSUBISHI: ACTROS 1832/
2646/2650/ 2654/2658
AXOR 2006/ 3344



GNP2235



D:20
L:110
P:14.7
E:5
C:60
CW

ZEN0887
MITSUBISHI:CANTER/
CATERPILLAR 320B



ZEN1679



D:21
L:131.3
P:16.5
E:7
AE:59.7
CW

DELCO:29MT AXOR 1933/
OM924/ OM926 CASE/MWM
PIÑON ZEN12954/55/56/57



ZEN1805



D:21
L:131.3
P:16.5
E:6
C:60
CW

DELCO:29MT VW 8-150/
PIÑON ZEN12954/55/56/57



ZEN1809  D:23 L:144.2 P:17.5 E:6 IP:13.01 C:69.5 DELCO: 38MT CUMMINS / FORD / SCANIA / PIÑON ZEN13130/ 13138	ZEN1810  D:28 L:148 P:20.1 E:6 IP:13.01 C:72.2 DELCO: 39MT - MACK / NEW HOLLAND / VOLVO / PIÑON ZEN13117/18/19	ZEN1811  D:23 L:144.2 P:17.5 E:6 IP:13.01 C:72.2 DELCO: 39MT - CASE / CUMMINS / NEW HOLLAND / PIÑON ZEN13130/ 31/32	ZEN1647  D:17 L:117.5 P:13.9 E:6 IP:12 C:60 CW PRESTOLITE: JOHN DEERE
ZEN1936  D:21 L:167.5 P:16.5 E:8 IP: C:60 CW DELCO: BENDIX + PLANETARIO 29MT AXOR 1419VW/ VOLVO	ZEN1803  D:13 L:97.85 P:34.65 E:16 IP:11 CCW BOSCH:VOLKSWAGEN FOX / GOLF / POLO / SEAT / SKODA	ZEN1824  D:33 L:87.3 P:17 E:4 IP:10 C:48.9 CCW VALEO AUDI / SKODA / VW GOLF / PASSAT TDI	ZEN1996  D:18 L:128.9 P:18.6 E:5 IP: C:72.2 CW HINO NP700
ZEN0815  D:9 L:99 P:39.3 DC:48 C:62 CW MITSUBA: HONDA CIVIC/ ACCORD/PRELUDE	ZEN1548  D:9 L:95.7 P:29.3 DC:61 C:63.1 CW MITSUBA:HONDA CIVIC 1.7 ACCURA 2001/2005	ZEN1473  D:40 L:80.5 P: E: IP: C:53.8 DENSO:HYSTER LIFT TK 4.3L/XL 80	ZEN1555  D:13 L:110 P:40.3 DC:40 C:53.8 DENSO:TOYOTA HILUX/ CELICA/ CAMRY PIÑON ZEN9506
ZEN1566  D:10 L:110 P: DC:40 C:53.8 CW HARLEY DAVIDSON PIÑON ZEN9492	ZEN1723  D:18 L:102 P:12.7 CCW DENSO:SUBARU 128000-7200 (STR8044)	ZEN1846  D:10 L:111 P:40.5 E: IP: C: DENSO:HYSTER	ZEN1905  D:11 L:133.5 P:34.8 DC:40 IP: C:53.8 CCW DENSO:KIA PREGIO 2.2
ZEN0750  D:11 L:83 P:29.3 DC:40 C:53.8 CW DENSO:CHRYSLER PIÑON ZEN9307 REPARACION ZEN1201	ZEN0816  D:10 L:83 P:33 DC:40 C:53.8 CW DENSO:TOYOTA/ DODGE RAM/ DAKOTA PIÑON ZEN9349	ZEN1601  D:11 L:102 P:34.4 DC:40 C:53.8 CW MANDO:KIA BESTA 2.5 2.7	GNP2219  D:9 L:102 P:29.6 DC:40 C:53.8 CW ZEN0947 DENSO:ROCKY F80/ TOYOTA 2S/2Y/HILUX/LUV PIÑON ZEN9186

ZEN0817   D:10 L:83 P:28.2 DC:40 C:53.8 CW DENSO:CHRYSLER DODGE CARAVAN 92/97 PIÑON ZEN9492	ZEN0818   D:9 L:83 P:29.6 DC:40 C:53.8 CW DENSO:HONDA/ YALE TOYOTA COROLLA/ISUZU PIÑON ZEN9186	ZEN0954   D:10 L:83 P:37.8 DC:40 C:53.8 CW DENSO:TOYOTA HILUX 2.8	ZEN2032   D:9 L:93.5 P:29.64 DC:40 C:53.8 CW DENSO:HYUNDAI SANTA FE/ TUCSON/ CERATO/
ZEN0921   D:11 L:102 P:40 DC:40 C:53.8 CW DENSO:TOYOTA HILUX 2.8/LAS CRUISER D REPARACION ZEN1215	ZEN0946   D:9 L:102 P:32.2 DC:40 C:53.8 CW DENSO:ISUZU D/ LUV JEEP RENEGADE	ZEN0947   D:9 L:102 P:29.6 DC:40 C:53.8 CW DENSO:ROCKY F80/ TOYOTA 2S/2Y/HILUX/LUV PIÑON ZEN9186	ZEN1097   D:10 L:102 P:37.8 DC:40 C:53.8 CW DENSO:TOYOTA HILUX 3.0 SW4
ZEN1957   D:11 L:102 P:29.3 DC:40 IP: C:53.8 CW DENSO:KUBOTA/ ISUZU	ZEN1972   D:9 L:102 P:34.8 DC:40 IP: C:53.8 CW DENSO:KUBOTA	ZEN1973   D:11 L:102 P:42 DC:40 IP: C:53.8 CW DENSO:KUBOTA	ZEN2030   D:10 L:104 P:32.8 DC:40 IP: C:53.8 CW DENSO:TERRACAN/CARNIVAL
ZEN1827   D:11 L:147 P:40 E: IP: C:58 CW DENSO TOYOTA DYNA	GNP2223   D:11 L:147 P:40 E: IP: C:58 CW DENSO: TOYOTA DYNA 	ZEN1829   D:13 L:147 P:39.5 E: IP: C:58 CW DENSO CASE	ZEN1830   D:12 L:147 P:45 E: IP: C:58 CW DENSO: TOYOTA: LAND CRUISER 4.2
ZEN1831   D:10 L:147 P:40 E: IP: C:58 CW DENSO: BOBCAT/ CATERPILLAR	DR8241   D:11 L:147 P:40 E: IP: C:58 CW DENSO: TOYOTA DYNA 	GNP2224   D:12 L:147 P:37 E: IP: C:58 CW DENSO: KIA 3500 / 3600 	ZEN1961   D:11 L:146.3 P:38.4 DC:35 IP: C:55.4 CW DENSO:KOMATSU FD20

ZEN1962

ZEN



D:11
L:146.3
P:40
DC:35
IP:
C:55.4
CW

DENSO:TOYOTA DYNA/HILUX
LAND CRUISER

ZEN1999

ZEN



D:11
L:126.2
P:40.6
DC:
IP:
C:64.6
CW

SAWAFUJI:HINO DUTRO/
TOYOTA DYNA

ZEN2104

ZEN



D:9
L:146.3
P:35.5
DC:35
IP:
C:55.4
CW

DENSO:TRACTORES KUBOTA

DR548125

ZEN



D:9
L:87
P:33
DC:41
C:53.2
CW

HITACHI:THERMO KING/
ISUZU

REPARACION ZEN1200



DR5483415

ZEN



D:20
L:110
P:14.7
E:5
C:60
CW

MITSUBISHI:CANTER/
CATERPILLAR 320B



DR548202

ZEN



D:9
L:102
P:29.6
DC:40
C:53.8
CW

DENSO:ROCKY F80/
TOYOTA 2S/2Y/HILUX/LUV

PIÑON ZEN9186



DR541403

ZEN



D:21
L:131.3
P:16.5
E:6
C:60
CW

DELCO:29MT VW 8-150/
9-150/AXOR/ FORD

PIÑON ZEN12954/55/56/57



DR19812

ZEN



D:10
L:95.3
P:39.15
DC:41
C:53.2
CW

HITACHI: NISSAN NAVARA

S14413C



ZEN1828

ZEN



D:35
L:91.9
P:
E:
IP:
C:55.4
CW

DENSO

ZEN1200

ZEN



D:41
L:50
C:53.2
CW

HITACHI:ISUZU
REPARACION REDUCTORES
ZEN0737 Y ZEN0792

ZEN1201

ZEN



D:40
L:52
C:53.8
CW

DENSO
REPARACION REDUCTORES
ZEN750

ZEN1207

ZEN



D:41
L:50
C:53.2
CW

HITACHI:NISSAN
REPARACION REDUCTORES
ZEN0793

ZEN1211

ZEN



D:41
L:50
C:53.2
CCW

HITACHI
REPARACION REDUCTORES
ZEN793

ZEN1215

ZEN



D:40
L:64
C:53.8
CW Y
CCW

DENSO
REPARACION REDUCTORES
ZEN791

ZEN1947

ZEN



D:41
L:53.5
P:
E:11
IP:
C:64.44
CW

HITACHI
ZEN1608